

**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE.**

No. SDW/HS/0022Date : 03/03/2022

It is certified that an inspection team headed by Mr. C.K. Das
Insp Hygen and purity quality Siliguri Water Supply Division (Name of Officers
with designation) from Water and Supply Division Siliguri (Name of
Department/Office) inspected the Barivasa Central School, Barivasa
P.O. Sahudangi Hat, Dist. Jalpaiguri (W.B.) (Name & Address of
the School) on 3rd March 22 and found that the Barivasa Central School
Barivasa P.O. Sahudangi Hat, Dist. Jalpaiguri (W.B.) (Name of school) has safe
drinking water facilities for the students and members of staff of the institution and is maintaining
the hygienic sanitation condition in the school building & the campus as per the norms
prescribed by the Central/State/U.T Govt.


The above valid for a period of 2 yrs.

Signature with Seal : C.K. Das
Name : Executive Engineer
Designation : Siliguri Water Supply Division,
P.H. Engineering Dte.


To

Principal
Barivasa Central School
Barivasa P.O. Sahudangi Hat Dist Jalpaiguri (W.B.)

(Name & Address of the Institution)


Principal
Baribhasha Central School
Baribhasha, Sahudangi Hat
Dist. JALPAIGURI

4


Secretary
Barivasa Central School
Barivasa, P.O. Sahudangi Hat
Dist. Jalpaiguri, Pin-735135